

# Inspection Photos

May 13, 2025

Operator: BMG Drilling - 7650

Location ID: 325388

Inspection Document #: 714002167

La Plata County, CO

Township: NENE 5 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: La Posta Canyon 4

Location ID: 325388



May 13, 2025  
240° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of the project area taken from the northern edge facing center.

API #: 067-06291

Inspection Photos  
Location Name: La Posta Canyon 4  
Location ID: 325388



**Photo 2.** Musk thistle observed on location.

Inspection Photos  
Location Name: La Posta Canyon 4  
Location ID: 325388



**Photo 3.** Patch of Canada Thistle observed on location.

Inspection Photos

Location Name: La Posta Canyon 4

Location ID: 325388

May 13, 2025  
193° S



**Photo 4.** Gully erosion persists on the southern edge of the project area. Sediment transport and deposition occurring and impacting establishment of vegetation in the central portion of the project area (see photo 5).



Inspection Photos

Location Name: La Posta Canyon 4

Location ID: 325388

May 13, 2025  
152° SE



**Photo 5.** Sediment deposition occurring in the central portion of the project area. Stormwater BMPs are needed at gully erosion.

Inspection Photos

Location Name: La Posta Canyon 4

Location ID: 325388

May 13, 2025  
337° NW



**Photo 6.** Northwest corner of the project area where vegetation is not progressing to 1004 standards. Additional seeding efforts are needed in this area.

API #: 067-06291



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: La Posta Canyon 4  
Location ID: 325388



**Photo 7.** View of old anchor and cable that remains on location.

Inspection Photos

Location Name: La Posta Canyon 4

Location ID: 325388



May 13, 2025  
125° SE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 8.** View of access road which has not been regraded/recontoured per rule 1004 however, vegetation is progressing on access road.

API #: 067-06291