

Inspection Photos

May 13, 2025

Operator: Conoco Phillips 19160

Location ID: 385889

Inspection Document #: 714002169

La Plata County, CO

Township: SENW 31 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

May 13, 2025
96° E



Photo 1. View of project area access road facing east.



Inspection Photos

Location Name: Argenta 34-10 31-1

Location ID: 385889

May 13, 2025
+37.147368,-107.974388
118° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the project area taken from the northern edge facing center.

API #: 067-08199

Inspection Photos
Location Name: Argenta 34-10 31-1
Location ID: 385889



Photo 3. View of disturbance vegetation transect.

Inspection Photos

Location Name: Argenta 34-10 31-1

Location ID: 385889



May 13, 2025
+37.147022,-107.972900
11° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of adjacent reference area facing north.

API #: 067-08199

Inspection Photos

Location Name: Argenta 34-10 31-1

Location ID: 385889



Photo 5. View of reference area vegetation transect and center point.

Inspection Photos

Location Name: Argenta 34-10 31-1

Location ID: 385889



Photo 6. Patch of Musk Thistle observed at the start of the access road.