

# Final Reclamation and Stormwater Inspection

May 13, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 415194

Location Name: TALON VIEW/6-9

Inspection Document #: 718600578

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: TALON VIEW/6-9  
Location ID: 415194



**Photo 1.** Looking north down the east side of the location. List B noxious weeds Canada thistle is present on the edge of the location.



**Photo 2.** Looking north across the wellbores. Some desirable vegetation has established and appears to be progressing towards 80% of the reference area.





Inspection Photos  
Location Name: TALON VIEW/6-9  
Location ID: 415194



**Photo 3.** Picture taken at the northeast corner of the location looking south across the wellbores. This area has lower vegetation establishment than surrounding areas and a patch of bare earth is present.



**Photo 4.** Looking west from the northeast corner of the location across the former tank battery. See photo 3 comments.





Inspection Photos  
Location Name: TALON VIEW/6-9  
Location ID: 415194



**Photo 5.** Looking west across the tank battery from the north side of the location. Some desirable vegetation has established in this area but may need additional reclamation work the reach 80% of the reference area.



**Photo 6.** Looking east across the tank battery. See photo 5 comments.





Inspection Photos  
Location Name: TALON VIEW/6-9  
Location ID: 415194



**Photo 7.** Reference vegetation to the south of the location.