

Interim Reclamation and Stormwater Inspection

May 13, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 335580

Location Name: CHRISTENSEN #4-9

Inspection Document #: 718600581

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CHRISTENSEN #4-9
Location ID: 335580



Photo 1. Looking across the wellbore.



Photo 2. Stained soil is present around the wellbore.



Inspection Photos
Location Name: CHRISTENSEN #4-9
Location ID: 335580



Photo 3. Picture taken on the east side of the pumpjack. Stained soil is present near the pumpjack and appears to be leaking from equipment.



Photo 4. Looking southeast from the wellbore at the interim area. Undesirable weedy species such as Kochia and Curly Dock area present. List B noxious weed Canada Thistle is also present. Weeds appear to be encroaching on the access road.



Inspection Photos
Location Name: CHRISTENSEN #4-9
Location ID: 335580



Photo 5. List B noxious weed Canada thistle near the center of the location.



Photo 6. Looking south across the tank battery.



Inspection Photos
Location Name: CHRISTENSEN #4-9
Location ID: 335580



Photo 7. Looking north at separator and ECD on location.



Photo 8. See photo 7 comments.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718600581