

Inspection Photos

May 13, 2025

Operator: Hilcorp Energy - 10133

Location ID: 333494

Inspection Document #: 714002170

La Plata County, CO

Township: NWSE 32 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

May 13, 2025
36° NE



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Argenta
Location ID: 333494



May 13, 2025
187° S

Photo 2. View of erosion issues in the southern portion of the pad facing south.



Photo 3. View of erosion issues in the southern portion of the location facing north.

May 13, 2025
281° W



Photo 4. Spill/stained soils observed at pumpjack equipment.

Inspection Photos
Location Name: Argenta
Location ID: 333494

May 13, 2025
31° NE



May 13, 2025
53° NE



Photo 6. Unused oil and gas equipment observed at the pumpjack.



Photo 7. Deep tunnel erosion forming on the western edge perimeter berm.

