

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

05/20/2025

Document Number:

403928250

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10805 Contact Person: Rikki Ross
Company Name: FULCRUM ENERGY OPERATING LLC Phone: (970) 896-5665
Address: 240 SAINT PAUL STREET SUITE 502 Fax: ()
City: DENVER State: CO Zip: 80206 Email: rikki.ross@fulcrumeo.com

Identification Information

API Number: 05 - - ECMC Facility ID: 458558 Initial Form 19 or 27 Document number:
Facility Name: Marmot 0880 Facility Number: S19 CTB Facility Type: LOCATION
Location QtrQtr: SESE Section: 19 Township: 8N Range: 80W Meridian: 6
County: JACKSON Field Name:
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: FULCRUM ENERGY OPERATING LLC Agent Name: Rikki Ross Title:
Phone Number: 970-896-5665 Email: rikki.ross@fulcrumeo.com

Rule 909.J Inspection Information

Date the Pit was Inspected
On inspection the Pit was: [] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 458558 Facility Name: Marmot 0880 S19 CTB Facility Type:
Location: QtrQtr: SESE Sec: 19 Twp: 8N Range: 80W Meridian: 6
County Name: JACKSON Latitude: 40.645891 Longitude: -106.409662

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 126636 Document Name: Size of file in bytes: 17970 File Name: 2024_07_23_Marmot VRU Scrubber Gas EDD.xlsx
SampleType: Matrix:
Facility ID: 458558 Sample ID: 667208 Sample Name: Marmot VRU Scrubber Gas Sample Date: 07/23/2024
Collection Point: SEP Matrix: GAS Pre Post: Production Gas Sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: American Mobile Research Lab Sample ID: CR-37

Batch ID: 126635 Document Name: Size of file in bytes: 17343 File Name: 2024_07_23_Marmot Separator Crude Oil EDD.xlsx
 SampleType: _____ Matrix: _____
 Facility ID: 458558 Sample ID: 667207 Sample Name: Marmot Separator Crude Oil Sample Date: 07/23/2024
 Collection Point: SEP Matrix: GAS Pre Post: Production Gas Sample
 Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____
 Inspection Number: _____ Spill Number: _____ Laboratory: American Mobile Research Lab Sample ID: CR-95

Batch ID: 126636 Document Name: Size of file in bytes: 17970 File Name: 2024_07_23_Marmot VRU Scrubber Gas EDD.xlsx
 SampleType: _____ Matrix: _____
 Facility ID: 458558 Sample ID: 667209 Sample Name: Marmot VRU Scrubber Gas 2 Sample Date: 07/23/2024
 Collection Point: SEP Matrix: GAS Pre Post: Production Gas Sample
 Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____
 Inspection Number: _____ Spill Number: _____ Laboratory: American Mobile Research Lab Sample ID: CR-38

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	05/20/2025
Environmental Data	RTD - PrePost does not align with Facility Type or analytical suite. EDD does not contain "Date Received" or "Laboratory."	05/14/2025
Total: 2 comment(s)		