

Inspection Photos

05/20/2025

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312661

Inspection Doc: 718100526

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312661



Photo 1: Photos 1-2 taken from north end of the Location. Photos provide an overview from east, southeast, southwest to west. Photos also show additional reclamation efforts on the Location are apparent. Site appears to be progressing towards ECMC 1004 revegetation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312661



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312661



Photo 3: Photos examples showing access road leading to the Location. Road has not been reclaimed in accordance with 1004 requirements. Operator filed a hearings application (docket #230900303) with a 502.b surface owner variance request from ECMC Rules 1004.a and 1004.d to leave the O&G Access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312661



Photo 4: Continued from photo 3. Photo shows additional reclamation and stabilization efforts are evident on the the cut slopes of the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources