

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Jolley/KP 24-8

Location ID: 336009

Date: 5/20/2025



May 20, 2025 at 12:31:00
New Castle CO 81647
United States

Location – Photo #08791



May 20, 2025 at 12:40:55
New Castle CO 81647
United States

Location – Photo #08813

Audit Photos
Location Name: TEP ROCKY MOUNTAIN LLC, Jolley/KP 24-8
Location ID: 336009
Date: 5/20/2025

Location ID: 336009

Date: 5/20/2025



Location – Photo #08793



Location – Photo #08803

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Jolley/KP 24-8

Location ID: 336009

Date: 5/20/2025



Location – Photo #08811



Location – Photo #08812

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Jolley/KP 24-8


Location ID: 336009

Date: 5/20/2025



May 20, 2025 at 12:45:15
New Castle CO 81647
United States

Location – Photo #08819



May 20, 2025 at 12:34:39
New Castle CO 81647
United States

Illegible Tank Label – Photo #08799

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Jolley/KP 24-8

Location ID: 336009

Date: 5/20/2025



Stored Supplies/Equipment – Photo #08814



PRV Terminates in Unsafe Manner – Photo #08798

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Jolley/KP 24-8

Location ID: 336009

Date: 5/20/2025



Lack of Stabilization – Photo #08816



Insufficient Tracking BMPs – Photo #08817