

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404215619

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 730-7281
City: DENVER State: CO Zip: 80202		Mobile: ()
Contact Person: Dan Peterson	Email: danpeterson@chevron.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 21830 Initial Form 27 Document #: 402944066

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: LOCATION	Facility ID: 323068	API #: _____	County Name: WELD
Facility Name: BRANCH-64N64W 3NENE	Latitude: 40.346798	Longitude: -104.529377	
** correct Lat/Long if needed: Latitude: 40.348379		Longitude: -104.530032	
QtrQtr: NENE	Sec: 3	Twp: 4N	Range: 64W Meridian: 6 Sensitive Area? Yes
Facility Type: SPILL OR RELEASE	Facility ID: 482385	API #: _____	County Name: WELD
Facility Name: Branch 1-3	Latitude: 40.348412	Longitude: -104.529767	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NENE	Sec: 3	Twp: 4N	Range: 64W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SW

Most Sensitive Adjacent Land Use Crop Land

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

HWY 0.01mi N
Residential 0.09/0.1/0.19mi E, 0.2/0.22mi S, 0.15mi SW, 0.25mi NE, 0.2mi W, 0.25mi N
Farm Structures 0.09/0.17/0.22mi E, 0.2mi SE, 0.14/0.17mi S, 0.23mi W
Freshwater Emergent Wetlands 0.23mi SW
No other potential receptors are located within 1/4 mile of the site.
Above distances are approximations.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	See attached figure	Laboratory analysis
Yes	SOILS	See attached figure	Laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation was conducted pursuant to COGCC Rule 911 at the BRANCH T4N-R64W-S3 L01 Tank Battery location.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Ten soil borings were advanced to determine extent of soil impacts due to an historical release from the facility's produced water vault. Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) and organic compounds in soil per COGCC Table 915-1. All samples collected were analyzed by a certified laboratory using approved COGCC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Not encountered

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil	NA / ND
Number of soil samples collected 41	-- Highest concentration of TPH (mg/kg) 9980
Number of soil samples exceeding 915-1 56	-- Highest concentration of SAR 11.4

Was the areal and vertical extent of soil contamination delineated? No

BTEX > 915-1 Yes

Approximate areal extent (square feet) 8000

Vertical Extent > 915-1 (in feet) 13

Groundwater

Number of groundwater samples collected 5

ND Highest concentration of Benzene (µg/l) _____

Was extent of groundwater contaminated delineated? Yes

ND Highest concentration of Toluene (µg/l) _____

Depth to groundwater (below ground surface, in feet) 10

ND Highest concentration of Ethylbenzene (µg/l) _____

Number of groundwater monitoring wells installed 5

ND Highest concentration of Xylene (µg/l) _____

Number of groundwater samples exceeding 915-1 0

NA Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

One background soil sample (BKG01@6") was collected from an area not impacted by oil and gas development and analyzed for Table 915 Soil Suitability constituents (pH, EC, SAR, and Boron) and Table 915 metals. The background soil sample was reported with elevated concentrations/values of SAR, Arsenic, and Selenium.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____

Volume of liquid waste (barrels) _____

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

As much of the source was removed as practicable by the conventional excavation of soil that exceeded Table 915-1 limits for organic compounds in soil.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Approximately 3,850 cubic yards of impacted soil was excavated and disposed of at Buffalo Ridge Landfill. Impacted, unsaturated soil identified on the North wall of the excavation along County Road 5 could not be removed due to overhead electric lines and telecom utilities. As described in the Groundwater Monitoring section, soil borings/monitoring wells were installed to delineate the lateral extent of the reported groundwater impacts in August 2024.

Three borings were advanced in the former excavation's North wall to determine if residual soil impacts present at 10 feet bgs. had naturally attenuated. Natural attenuation has successfully remediated soil impacts initially observed in N01 10', N02 10', and N03 10' excavation confirmation sample locations based on the lab results for samples collected on 8/16/2024.

NFA will be requested once four consecutive quarters of groundwater sampling have been completed and reported at the location with concentrations of Table 915-1 constituents below regulatory limits. As needed, soil and/or groundwater remediation plans will be developed and submitted to ECMC in a supplemental Form 27.

Soil Remediation Summary

In Situ

Ex Situ

Bioremediation (or enhanced bioremediation)

Chemical oxidation
 Air sparge / Soil vapor extraction
 Yes Natural Attenuation
 Other _____

Yes Excavate and offsite disposal
 If Yes: Estimated Volume (Cubic Yards) _____ 3850
 Name of Licensed Disposal Facility or ECMC Facility ID # _____
 Excavate and onsite remediation
 Land Treatment
 Bioremediation (or enhanced bioremediation)
 Chemical oxidation
 Other _____

Groundwater Remediation Summary

Bioremediation (or enhanced bioremediation)
 Chemical oxidation
 Air sparge / Soil vapor extraction
 Yes Natural Attenuation
 Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater will be sampled on a quarterly basis until analytical results are reported with concentrations of Table 915-1 analytes below regulatory limits for four consecutive quarters. Five monitoring wells (MW-1 through MW-5) are sampled on a quarterly basis to monitor (natural) attenuation. Groundwater monitoring wells were sampled and submitted to a laboratory for analysis of Table 915-1 groundwater constituents: Benzene, Toluene, Ethylbenzene, Total Xylenes (BTEX), naphthalene, 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene, Chloride ion, Sulfate ion and Total Dissolved Solids (TDS).

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other _____

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).
If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 25000 _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

No beneficial use.

Volume of E&P Waste (solid) in cubic yards _____ 3850

E&P waste (solid) description _____ Impacted Soil _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____ WM Buffalo Ridge Landfill _____

Volume of E&P Waste (liquid) in barrels _____ 0

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

If YES:

- Compliant with Rule 913.h.(1).
- Compliant with Rule 913.h.(2).
- Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 06/29/2022

Proposed date of completion of Reclamation. 12/31/2026

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 07/29/2021

Actual Spill or Release date, or date of discovery. 06/20/2022

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 06/29/2022

Proposed site investigation commencement. 02/14/2022

Proposed completion of site investigation. 06/29/2022

REMEDIAL ACTION DATES

Proposed start date of Remediation. 09/26/2022

Proposed date of completion of Remediation. 12/31/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

This form updates the ECMC with data collected at the location during the Q1 2025 groundwater sampling, which was completed on February 5, 2025.

This form also serves to address the COA from document # 404101768:

The work plan has been implemented as proposed in the Remedial Action Plan section. Monitoring wells (MW-1 through MW-5) at the location have been sampled on a quarterly basis and analyzed for all Table 915-1 constituents in groundwater. The comment in the Site Investigation Report section "Is further site investigation required? - Additional investigation needs to be completed to delineate the extent of the reported groundwater impacts." was left in the form by error following the excavation SF27 update for the location. Additional investigation was thought to have been achieved when monitoring wells (MW-1 through MW-5) and soil borings [N01 (2), N02 (2) and N03 (2)] were installed in August 2024. The monitoring wells were installed to monitor groundwater conditions and the soil borings were installed to confirm the natural attenuation of organic soil impacts identified on the North wall of the excavation. The confirmation soil samples confirmed that organic impacts no longer remained at the previously impacted sample locations.

The groundwater sample that was collected from the excavation (GW01) has been added to the groundwater figures to show where it was collected spatially in relation to the monitoring well network. The GW01 sample location falls approximately where MW-2 was installed. Monitoring well MW-2 has been sampled for three consecutive quarters with no detections for Table 915-1 organic compounds. To address concerns about POC, two additional monitoring wells are proposed to be installed downgradient of MW-2 to the northeast and northwest. Find the proposed monitoring well map attached. Locations for the additional monitoring wells are limited due to a road, significant utility presence in the area, and topography. See the attached photolog for context. The additional monitoring wells are tentatively scheduled to be installed by June 20, 2025.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Chris Lattes

Title: Consultant

Submit Date: _____

Email: chrisl@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

Remediation Project Number: 21830

COA Type

Description

0 COA	
-------	--

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

404215715	MONITORING REPORT
404215716	LABORATORY ANALYTICAL REPORT
404215717	MAP
404215718	PHOTO DOCUMENTATION

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)