

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Dutch Lake 24-22H

Loc ID: 430123

Inspection: 696307624



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Tumbleweeds at Tank Berm. Comply with Rule 606.

CA Resolution: Operator has addressed the issue in order to comply with Rule 606

CA: Weeds on Location and inside Tank Berm; see photos. Comply with Rule 606.

CA Resolution: Operator has addressed the issue in order to comply with Rule 606