

# Final Reclamation and Stormwater Inspection

May 13, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 320470

Location Name: MCELWAIN #13-17

Inspection Document #: 718600587

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MCELWAIN #13-17  
Location ID: 320470



**Photo 1.** Looking west down the access road. Entrance has been recontoured and a new road and curb constructed



**Photo 2.** Looking north across the tank battery. Equipment has been removed. It does not appear that reclamation has been conducted on the tank battery location. Gravel remain on location. Large bare areas are present. Undesirable weeds such as Kochia and Cheatgrass are present on location.





Inspection Photos  
Location Name: MCELWAIN #13-17  
Location ID: 320470



**Photo 3.** Photo taken at the north side of the tank battery. Illustrating gravel remaining and large bare patch.



**Photo 4.** Looking east down the access road between the tank battery and well location. Undesirable weeds such as Cheatgrass are present along the access road.





Inspection Photos  
Location Name: MCELWAIN #13-17  
Location ID: 320470



**Photo 5.** 3" chunks of concrete rip rap are present along the former access road including in the fallow field for approximately 100 feet along the former access road.



**Photo 6.** Looking north across the well location. All oil and gas equipment has been removed. Desirable perennial vegetation appears to have established and is progressing towards 80% of the reference area. The well location is surrounded by fallow cropland.





Inspection Photos  
Location Name: MCELWAIN #13-17  
Location ID: 320470



**Photo 7.** Looking east from the wellbore. See photo 6 comments.



**Photo 8.** Looking south from the wellbore. See photo 6 comments.





Inspection Photos  
Location Name: MCELWAIN #13-17  
Location ID: 320470



**Photo 9.** Looking west from the wellbore. See photo 6 comments.



**Photo 10.** Reference vegetation to the east of the wellbore.





Inspection Photos  
Location Name: MCELWAIN #13-17  
Location ID: 320470



**Photo 11.** Google earth aerial imagery taken 10/1999. the well and part of tank battery area (green circles) appears to have been cropland before location construction.