

Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
AMATO WW 1-19 (2025 Seasonal)	Spring	Marco Gonzalez	5/22/2025
Work Summary	Reclamation Type	Land Use	
Innerseeded site	Final Maint	Other	
One-Call Number	Red Zone Rep	Red Zone Date	

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance		No	Location(s): AMATO WW 1-19 Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **21,780 sq ft**
Seed Mix: **Sandy Soil 2 (10.00 lbs)**
Crop Type:
Soil Type: **Sandy**
Stabilization Date:
Seeding Date: **5/22/2025**
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes: **Job oxrm1014**

PHOTOS

Photo Name: Site Map

Description:

12:49 PM Thu May 22

AMATO WW 1-19

Latitude: 40.084181

Longitude: -104.729206

Altitude: 0 Feet

Found At: 4/28/2025 7:51:12 AM

AMATO_WW-61N66W_1NENW

View Fullscreen

AMATO WW 1-19

my location

Speer Canal

+

-

17

Logged In

Oxy 1

Maps

Photo Name: Seed Mix
Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:

