

Inspection Photos

May 14th, 2025

Operator: Highpoint Operating - 10071

Location ID: 313631

Inspection Document #: 714002180

Montezuma County, CO

Township: SESE 28 38N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631



May 14, 2025
173° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the northern edge facing center.

API #:083-06656

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631

May 14, 2025
3° N



May 14, 2025
80° E



Photo 2. Cardinal photos taken from the center of the project area; left photo facing north, right photo facing east.

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631



Photo 3. Cardinal photos taken from the center of the project area; left photo facing south, right photo facing west. Note: Location dominated by large patches of cheatgrass.

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631



May 14, 2025
334° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of reference area. Note: no Cheatgrass was observed in the adjacent reference area.

API #:083-06656

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631

May 14, 2025
179° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Musk thistle observed at access road.

API #:083-06656