

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GGU 13-28 Pad
Location ID: 335245



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas & in close proximity
to NSO Habitat area.**

Section/Township/Range: 28 6S91W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GGU 13-28 Pad
Location ID: 335245



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GGU 13-28 Pad
Location ID: 335245



Photo # 3001 Failure to maintain chemical BMP - Chemical tank containment approximately 2/3 to 3/4 full of fluid/BMP insufficient to contain possible spill



Photo # 3002 Failure to maintain chemical BMP - Chemical tank containment approximately 2/3 to 3/4 full of fluid/BMP insufficient to contain possible spill