

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, JOLLEY/KP 43-8

Location ID: 412676

Date: 5/20/2025



**Location Overview/Lack of Stabilization/Insufficient Tracking
BMPs – Photo #08856**



Location – Photo #08857

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, JOLLEY/KP 43-8

Location ID: 412676

Date: 5/20/2025



Location – Photo #08875



Location – Photo #08861

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, JOLLEY/KP 43-8

Location ID: 412676

Date: 5/20/2025



Illegible Wellhead Sign – Photo #08858

Illegible Wellhead Sign – Photo #08859

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, JOLLEY/KP 43-8

Location ID: 412676

Date: 5/20/2025



Illegible Wellhead Sign – Photo #08860



PRV Terminates in Unsafe Manner – Photo #08864

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, JOLLEY/KP 43-8

Location ID: 412676

Date: 5/20/2025



PRV Terminates in Unsafe Manner – Photo #08867



PRV Terminates in Unsafe Manner – Photo #08871