

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 2110 From entrance to location




Photo # 2111 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 2112 Location




Photo # 2113 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 2114 Location



Photo # 2115 Weeds in secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 2116 Weeds in secondary containment




Photo # 2117 Weeds in secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 2118 Hole near wellhead/wildlife & personnel hazard



Photo # 2119 Hole near wellhead/wildlife & personnel hazard