

Inspection Photos
Location Name: Salvador 2-5
API Number: 125-06612



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Salvador 2-5
API Number: 125-06612



3. Lease signs at gathering location.



4. Incorrect Lease sign at gathering location for API 05-125-06612.

Inspection Photos Location Name: Salvador 2-5 API Number: 125-06612

Station ID# 7115217		Lease Name SALVADOR 6-5		Differential Inches in H ₂ O	
Cal SP Span 0-400#		Federal or State ID# 125-06612		Static PSIG	
Cal DP span 0-250"		Section 5	Township 4N	Range 46W	Temperature In Fahrenheit
SP Range 0-800#	Temp Range -40° to 160°	Contract Hour 8		Tap Location Downstream	
DP Range 0-250"	Atm Pressure 12.7	Pressure Base 14.73			
Tech	Cal Date	Orifice Bore			
	CAL 1/28/20				
	.375 NB				
	PLT CHG 9/28/20				
	.375 TO .25 NB				
	CAL 3-8-21				
	NB .25				
BJ 11/28/2022 .250					
BJ 03/18/2024 .250					
LW 4/10/2025 .250					

2025.05.20 11:58

5. Gas Meter Calibration/Log inside remote meter shed with incorrect Lease name for API 05-125-06612.



6. Gathering location overview.