

Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329895

Inspection Document #: 718800300

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PSC #23-11
Location ID: 329895



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. Photo illustrates that bare ground patches remain at the location. However, based on Google Earth Aerial Imagery, disturbances appear to be caused by development adjacent to the well location (See Photo 3).



Inspection Photos
Location Name: PSC #23-11
Location ID: 329895



Photo 3. Photo taken from the well location, facing South. Disturbances at the location appear to be related to development adjacent to the well site (circled in red).



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: PSC #23-11
Location ID: 329895



Photo 5. Photo taken of the reference area, east of the well site, facing Northeast. Photo illustrates perennial grass vegetation.

