

Final Reclamation Inspection

May 9, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 330078

Inspection Document #: 718800319

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: NORGREN #14-16J7
Location ID: 330078



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of seeding and straw mulch, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: NORGREN #14-16J7
Location ID: 330078



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: NORGREN #14-16J7
Location ID: 330078



Photo 5. Photo taken from the access road, facing East towards the well location. Photo illustrates that final reclamation activities have not taken place along the access road.



Photo 6. Photo taken of the access road, facing West. See comments under Photo 5.



Inspection Photos
Location Name: NORGREN #14-16J7
Location ID: 330078



Photo 7. Photo taken of the reference area, south of the well location, facing South. Photo illustrates perennial grass vegetation.

