

Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
HSR-ATLER 10-5, HSR-ATLER FEDERAL 9-5A (2025 Seasonal)	Spring	Marco Gonzalez	5/23/2025

Work Summary	Reclamation Type	Land Use
Innerseeded site	Final Maint	Other

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance		No	Location(s): HSR_ALTER_FEDERAL-61N66W_5NESE Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **65,340 sq ft**
 Seed Mix: **Sandy Soil 2 (20.00 lbs)**
 Crop Type:
 Soil Type: **Sandy**
 Stabilization Date:
 Seeding Date: **5/23/2025**
 Mulch: **None**
 Straw Bales: **NA**
 Soil Amendment Type: **None**
 Soil Amendment Rate: **NA**
 Imported Top Soil: **NA**
 Top Soil Source: **NA**
 General Notes: **Job oxrm1243**

PHOTOS

Photo Name: Site Map

Description:




Photo Name: Seed Mix

Description:




Photo Name: Pre-Completion


Description:



Photo Name: Post-Completion

Description:





HSR ATLER FEDERAL 9-

HSR-ATLER 10-5 NB-CD