

Final Reclamation Inspection

May 15, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 323717

Inspection Document #: 718800326

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BOHLENDER #D20-3
Location ID: 323717



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: BOHLENDER #D20-3
Location ID: 323717



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: BOHLENDER #D20-3
Location ID: 323717



Photo 5. Photo taken from the access road, facing West towards the well location. Photo illustrates that weedy annual vegetation and bare ground remain along the access road.



Photo 6. Photo taken of vegetation along the access road. Photo illustrates that cheatgrass (*Bromus tectorum*) is present across the location and is a List C noxious weed species.



Inspection Photos
Location Name: BOHLENDER #D20-3
Location ID: 323717



Photo 7. Photo taken of the reference area, east of the location, facing North. Photo illustrates some perennial vegetation and weedy annual growth including cheatgrass (*Bromus tectorum*).

