

# Final Reclamation Inspection

May 15, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329385

Inspection Document #: 718800343

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DECHANT #D 7-9  
Location ID: 329385



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: DECHANT #D 7-9  
Location ID: 329385



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: DECHANT #D 7-9  
Location ID: 329385



**Photo 5.** Photo taken from the reference area, northwest of the well location, facing North. Photo illustrates perennial grass vegetation as well as the presence of cheatgrass (*Bromus tectorum*).

