

Final Reclamation Inspection

May 15, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 305423

Inspection Document #: 718800347

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DECHANT D #7-23
Location ID: 305423



Photo 1. Photo taken from the well location, facing North. Photo illustrates that the location does not meet Rule 1004 reclamation standards as vegetation has not established.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DECHANT D #7-23
Location ID: 305423



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DECHANT D #7-23
Location ID: 305423



Photo 5. Photo taken from the access road, facing West towards the well location. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards. Cheatgrass (*Bromus tectorum*) is present across the access road and is a List C noxious weed species.



Photo 6. Photo taken from the access road, facing North, away from the well location. See comments under Photo 5.



Inspection Photos
Location Name: DECHANT D #7-23
Location ID: 305423



Photo 7. Photo taken from the reference area, east of the well location, facing Northeast. Photo illustrates cheatgrass (*Bromus tectorum*) is present throughout the reference area.