

Final Reclamation and Stormwater Inspection

May 21, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320562

Well Name: CO STATE A #44-36

Inspection Document #: 718600611

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CO STATE A #44-36

Location ID: 320562



Photo 1. Looking north down the access road. The two tracks is visible with bare ground present. Undesirable weed kochia is present on portions of the access road.



Photo 2. Looking east across the tank battery location. All oil and gas equipment has been removed. Desirable vegetation is established on most of the tank battery location and appears to be progressing towards 80% coverage of the reference area. Undesirable weed kochia and list B noxious weed scotch thistle are present on location.



Inspection Photos
Location Name: CO STATE A #44-36
Location ID: 320562



Photo 3. Looking west across the location from the east side.
See photo 2 comments.



Photo 4. Picture taken looking north from the center of the south side of the location. A large patch of kochia with less desirable vegetation establishment is present in the center of the location.



Inspection Photos
Location Name: CO STATE A #44-36
Location ID: 320562



Photo 5. Looking northwest across the wellbore are. Some desirable vegetation has established in this area. List B noxious weed scotch thistle and list C noxious weed cheatgrass is present on location.



Photo 6. Looking north from the wellbore. See photo 5 comments.



Inspection Photos
Location Name: CO STATE A #44-36
Location ID: 320562



Photo 7. Looking east from the wellbore. See photo 5 comments.



Photo 8. Looking south from the wellbore. See photo 5 comments.



Inspection Photos
Location Name: CO STATE A #44-36
Location ID: 320562



Photo 9. Reference vegetation to the north of the tank battery location.