

Final Reclamation and Stormwater Inspection

May 21, 2025

Operator: EXTRACTION OIL & GAS INC

Location ID: 452648

Location Name: Colorado State A/CTB

Inspection Document #: 718600599

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Colorado State A/CTB
Location ID: 452648



Photo 1. Looking west from the center of location. Desirable vegetation appears to be primarily Canada wild rye and appears to be progressing on the south side of the location.



Photo 2. Looking west across the south side of the location. Desirable vegetation is present. Undesirable weeds such as Russian thistle are present on location.



Inspection Photos
Location Name: Colorado State A/CTB
Location ID: 452648



Photo 3. Looking south down the south access road. All access roads remain.



Photo 4. Looking south across the east side of the location. Desirable vegetation is present but has lower coverage in this area.

Inspection Photos
Location Name: Colorado State A/CTB
Location ID: 452648



Photo 5. Looking at the east side of location. See photo 4 comments.



Photo 6. Looking west across the north side of the location. There is little perennial vegetation establishment in this area.



Inspection Photos
Location Name: Colorado State A/CTB
Location ID: 452648



Photo 7. Reference vegetation to the south of the tank battery.