

Final Reclamation and Stormwater Inspection

May 21, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 319798

Well Name: STATE A #4

Inspection Document #: 718600601

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE A #4
Location ID: 319798



Photo 1. Looking South down the access road towards the well location. Access road vegetation is primarily undesirable weed russian thistle and list C noxious weed field bindweed. Little to no desirable vegetation is present on the access road.



Photo 2. Photo taken at midpoint of access road looking south. Illustrating undesirable weedy vegetation coverage.



Inspection Photos
Location Name: STATE A #4
Location ID: 319798



Photo 3. Looking east across the well location. Equipment remains on location.



Photo 4. Picture taken on the east side of location. Electrical box and posts remain on location.



Inspection Photos
Location Name: STATE A #4
Location ID: 319798



Photo 5. Looking south across the location. Vegetation on the location is primarily undesirable weed russian thistle. Canada wild rye is sparsely present across the location. Desirable vegetation establishment appears to be poor across location.



Photo 6. Photo taken from center of location. Illustrating vegetation present on location.



Inspection Photos
Location Name: STATE A #4
Location ID: 319798



Photo 7. Closeup of primary vegetation on location, russian thistle.



Photo 8. Looking west from the wellbore. Very little desirable vegetation is present. Vegetation is primarily undesirable weed russian thistle.

Inspection Photos
Location Name: STATE A #4
Location ID: 319798



Photo 9. Looking north from the wellbore. See photo 8 comments.



Photo 10. Looking north from the wellbore. See photo 8 comments.

Inspection Photos
Location Name: STATE A #4
Location ID: 319798



Photo 11. Aerial photo taken Apr 2, 2024. Before reclamation activity (red circle).



Photo 12. Aerial photo taken Apr 30, 2024. Appears that reclamation was conducted on this location (red circle) and several others in the area.



Inspection Photos
Location Name: STATE A #4
Location ID: 319798



Photo 13. Reference vegetation to the west of the location.