

# Final Reclamation and Stormwater Inspection

May 21, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320548

Well Name: CO STATE A #33-36

Inspection Document #: 718600605

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CO STATE A #33-36  
Location ID: 320548



**Photo 1.** Looking west down the access road towards the well location. Access road vegetation is primarily undesirable weed russian thistle and list C noxious weed cheatgrass. Little to no desirable vegetation is present on the access road.



**Photo 2.** Looking northwest across the well location. Vegetation on location is primarily undesirable weedy vegetation russian thistle. Desirable vegetation establishment appears to be very poor across location.



Inspection Photos  
Location Name: CO STATE A #33-36  
Location ID: 320548



**Photo 3.** Looking east from the wellbore. See photo 2 comments.



**Photo 4.** Looking north from the wellbore. See photo 2 comments.



Inspection Photos  
Location Name: CO STATE A #33-36  
Location ID: 320548



**Photo 5.** Looking west from the wellbore. See photo 2 comments.



**Photo 6.** Looking south from the wellbore. See photo 2 comments.



**Inspection Photos**  
**Location Name: CO STATE A #33-36**  
**Location ID: 320548**



**Photo 7.** Aerial photo taken Apr 2, 2024. Before reclamation activity (red circle).



**Photo 8.** Aerial photo taken Apr 30, 2024. Appears that reclamation was conducted on this location (red circle) and several others in the area.



Inspection Photos  
Location Name: CO STATE A #33-36  
Location ID: 320548



**Photo 9.** Reference vegetation to the north of the location. Reference vegetation is primarily cheatgrass and tall tumble mustard.