

# Final Reclamation and Stormwater Inspection

May 21, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 319795

Well Name: STATE A #3

Inspection Document #: 718600607

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795



**Photo 1.** Looking south down the access road towards the well location. Access road vegetation is primarily undesirable weeds russian thistle and kochia. Little to no desirable vegetation is present on the access road.



**Photo 2.** Picture taken at mid point of access road looking south. Illustrating vegetative cover.



Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795



**Photo 3.** Looking south across the location. Location is primarily undesirable weed russian thistle. Very little desirable vegetation has established on location.



**Photo 4.** Picture taken in the center of location looking west, illustrating vegetation on location.



Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795



**Photo 5.** Looking west from the wellbore. See photo 3 comments.



**Photo 6.** Looking south from the wellbore. See photo 3 comments.



Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795



**Photo 7.** Looking east from the wellbore. See photo 3 comments.



**Photo 8.** Looking north from the wellbore. See photo 3 comments.



**Inspection Photos**  
**Location Name: STATE A #3**  
**Location ID: 319795**



**Photo 9.** Aerial photo taken Apr 2, 2024. Before reclamation activity (red circle).



**Photo 10.** Aerial photo taken Apr 30, 2024. Appears that reclamation was conducted on this location (red circle) and several others in the area.



Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795



**Photo 11.** Reference vegetation to the east of the location.