

Inspection Photos
Location Name: Darlene East 29N-20-11C
Location ID: 452153



Photo 1 – Signs at Entrance

Photo 2 – Location Overview

Inspection Photos
Location Name: Darlene East 29N-20-11C
Location ID: 452153




Photo 3 – Pumping Unit

Photo 4 – Wellhead Sign

Inspection Photos
Location Name: Darlene East 29N-20-11C
Location ID: 452153




Photo 5 – Wellhead



Photo 6 – Pumping Unit

Inspection Photos
Location Name: Darlene East 29N-20-11C
Location ID: 452153



Photo 7 – Maintenance Tank



Photo 8 – Tank Battery

Inspection Photos
Location Name: Darlene East 29N-20-11C
Location ID: 452153



Photo 9 – Water Tank Signage updated

Photo 10 – Tank Battery Signs

Inspection Photos
Location Name: Darlene East 29N-20-11C
Location ID: 452153



Photo 11 – ECDs



Photo 12 – Separator

Inspection Photos
Location Name: Darlene East 29N-20-11C
Location ID: 452153




Photo 13 – Flare



Photo 14 – Gas Meters