

Inspection Photos
Location: Red Rocks 35-11
Location ID: 484360, Rem
34161 API # 05-071-09929



Photo 1 –Well placard

Photo 2 – Wellhead, fencing needs maintained

Inspection Photos

Location: Red Rocks 35-11

Location ID: 484360, Rem

34161 API # 05-071-09929



Photo 3 – Noxious weeds and undesirable plants observed at the time of inspection

Photo 4 – BMPs need maintenance.

Inspection Photos

Location: Red Rocks 35-11

Location ID: 484360, Rem

34161 API # 05-071-09929



Photo 5 – Spill area looking southeast to wellhead



Photo 6 – Spill area 2 looking north, at the time of inspection pieces of blue tarp material were observed.