

TEP
KP 41-28
Location ID: 423258



Location



Location

TEP
KP 41-28
Location ID: 423258



May 21, 2025 at 11:38:11 AM
+39.505808,-107.551158 ±3.54r
ECM

Location




May 21, 2025 at 11:43:42 AM
+39.506133,-107.551196 ±3.60r
ECM

Location

TEP
KP 41-28
Location ID: 423258



Location



Location

TEP
KP 41-28
Location ID: 423258



Cut slope erosion



Cut slope erosion

TEP
KP 41-28
Location ID: 423258



Cut slope erosion



Cut slope erosion

TEP
KP 41-28
Location ID: 423258



Previous inspection photo



C/A from previous inspection completed

TEP
KP 41-28
Location ID: 423258



Previous inspection photo



C/A from previous inspection completed

TEP
KP 41-28
Location ID: 423258



Previous inspection photo




C/A from previous inspection completed

TEP
KP 41-28
Location ID: 423258



C/A from previous inspection completed



C/A from previous inspection completed

TEP
KP 41-28
Location ID: 423258



May 21, 2025 at 11:49:48 AM
+39.505612,-107.550969 ±2.85r
ECM

1 cap missing