

Inspection Photos
Location Name: Stults 33-32
API Number: 125-07659



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Stults 33-32
API Number: 125-07659



3. Well location overview



4. Lease sign at gathering location.

Inspection Photos
Location Name: Stults 33-32
API Number: 125-07659



5. View of fencing at metering location.



6. Gas Meter and Separator inside shed.