

# Inspection Photos

May 8th, 2025

Operator: BP America Production Company -  
10000

Location ID: 413525

Inspection Document #: 714002151

La Plata County, CO

Township: NWSW 21 35W 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Lewis 2  
Location ID: 413525

May 8, 2025  
340° N



**Photo 1.** View of the project area taken from the southern edge facing center.

Inspection Photos  
Location Name: Lewis 2  
Location ID:413525

May 8, 2025  
188° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of project area access road facing south.

API #: 067-09747

Inspection Photos  
Location Name: Lewis 2  
Location ID:413525

May 8, 2025  
189° S



**Photo 3.** View of perimeter fence that remains on location.

