



00209705

C

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION FORM

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
API No. 05- <u>123 - 18908</u>	LEASE NAME: <u>HSR-Brandt-Susie</u>
LOCATION: <u>NENE 3-7N-6W</u>	OPERATOR: <u>HS Resources</u>
DATE: <u>3-8-95</u> <u>12:00 PM</u> <u>NEED</u>	INSPECTOR: <u>E. B. Binkley</u> <u>8424465</u> <u>NE AREA</u>
Insp. Type: <u>CA</u>	Insp. Status: <u>DG</u>
PA: Y <input type="checkbox"/> N <input type="checkbox"/>	Pass/Fail: P <input checked="" type="checkbox"/> F <input type="checkbox"/>
Viol.: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	NOV: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs	<u>Rig Signs</u>	
Pits (Reserve/Production)	<u>Drill pits open</u>	
Fences	<u>✓ line around location</u>	
Tank Battery Equipment		
Fire Walls/Berms/Dikes		
General Housekeeping		
Spills (Oil/Water)	<u>At W water service</u> <u>Hauling mud to field 600'</u> <u>west of location.</u>	
Bradenhead	<u>consultant - mark <u>Seannillo</u></u> <u>[Goolsby Bros.]</u>	
Drilling Well/Workover	<u>Exeter Rig 14, Halliburton</u>	
Surface Rehabilitation	<u>plugging well. 40 5x 7125, 40 5x 3548</u> <u>40 5x 565 KB, 10 5x 40'</u>	
Miscellaneous	<u>Native grassland surface.</u>	

**CORRECTIVE ACTION REQUIRED:**

Notify AREA ENGINEER within 24 hours of spud on each permit

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.