



Closure Checklist

Closure Type: Wellhead Closure

Site Name: Mayne 2-10A

Remediation #:: 39999

Latitude, Longitude:: 40.244920, -104.760940

General Condition of Site: Good

USCS Soil Type: SC - Sands with fines - sand/clay mixture

Estimated Depth of Groundwater **more than 20' bgs**

Hydrocarbon Impacted Soils/Spills **None Observed**

Salt Crusted Soils or Impacted Vegetation **None Observed**

Soil Samples

#	Date	Time	Sample ID	PID	Visual	Olfactory	Equipment	Lab
1	05/09/2025	11:40	WH-B01@6'	1.7	No Staining	No odor	Wellhead	Yes
2	05/09/2025	11:40	WH-B01-01@6'	1.7	No Staining	No odor	Wellhead	Yes
3	05/09/2025	11:42	WH-RIS@4'	1.1	Strong Staining	No odor	Flowline at Wellhead	Yes
4	05/09/2025	11:42	WH-RIS-01@4'	1.1	Strong Staining	No odor	Flowline at Wellhead	Yes
5	05/09/2025	11:44	WH-N01@5'	2.9	No Staining	No odor	Wellhead	No
6	05/09/2025	11:48	WH-E01@5'	3.0	No Staining	No odor	Wellhead	No
7	05/09/2025	11:46	WH-S01@5'	2.7	No Staining	No odor	Wellhead	No
8	05/09/2025	11:50	WH-W01@5'	2.8	No Staining	No odor	Wellhead	No
9	05/09/2025	11:52	WHS-N01@3"	2.4	No Staining	No odor	Wellhead Surface	No
10	05/09/2025	11:56	WHS-E01@3"	2.2	No Staining	No odor	Wellhead Surface	No
11	05/09/2025	11:54	WHS-S01@3"	1.5	No Staining	No odor	Wellhead Surface	No
12	05/09/2025	11:58	WHS-W01@3"	2.7	No Staining	No odor	Wellhead Surface	No
13	05/09/2025	12:00	WH-BG01@3'	1.8	No Staining	No odor	Wellhead Background	Yes
14	05/09/2025	12:02	WH-BG01@6'	2.3	No Staining	No odor	Wellhead Background	Yes
15	05/09/2025	12:04	WH-BG02@3'	2.5	No Staining	No odor	Wellhead Background	Yes
16	05/09/2025	12:06	WH-BG02@6'	2.8	No Staining	No odor	Wellhead Background	Yes
17	05/09/2025	12:08	WH-BG03@3'	2.6	No Staining	No odor	Wellhead Background	Yes
18	05/09/2025	12:10	WH-BG03@6'	2.0	No Staining	No odor	Wellhead Background	Yes

19	05/09/2025	12:12	WH-BG04@3'	3.8	No Staining	No odor	Wellhead Background	Yes
20	05/09/2025	12:14	WH-BG04@6'	3.1	No Staining	No odor	Wellhead Background	Yes

1 - P1



Facing North

3 - P1



Looking South

6 - P1



Looking East

8 - P1



Looking West

13 - P1



Looking East

15 - P1



Looking West

17 - P1



Looking Northwest

19 - P1



Looking East

Was impacted soil identified?: No

Total number of soil samples field screened: 20

Total number of soil samples collected: 20

Highest PID reading: 3.8

Total number of soil samples submitted for analysis: 12

Was groundwater encountered during the investigation **No**

Measured Depth to Groundwater:

Was remedial groundwater removal conducted?

Date groundwater was encountered:

Commencement date of removal:

Sheen on groundwater?

Free product observed?

Volume of groundwater removed prior to sampling:

Volume of groundwater removed post

sampling:

**Total volume of
groundwater
removed:**

**Total volume of
groundwater
samples collected:**

**Total volume of
groundwater
samples submitted
to lab for analysis:**

Signature

A handwritten signature in black ink, appearing to read "John J. [unclear]", written in a cursive style.