

## Inspection Photos

Location Name: Camenisch 1 sx Flowline Release & Camenisch 1sx New Release

Spill ID: 479713 & 482375



Excavation w/ fencing



Inside the excavation. Weeds





## Inspection Photos

Location Name: Camenisch 1 sx Flowline Release & Camenisch 1sx New Release  
Spill ID: 479713 & 482375



Inside the excavation. Weeds and trash



Unplugged flowlines within the excavation





## Inspection Photos

Location Name: Camenisch 1 sx Flowline Release & Camenisch 1sx New Release  
Spill ID: 479713 & 482375



Weeds at the facility



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Camenisch 1 sx Flowline Release & Camenisch 1sx New Release

Spill ID: 479713 & 482375



Weeds at the facility



Weeds at the facility



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources



## Inspection Photos

Location Name: Camenisch 1 sx Flowline Release & Camenisch 1sx New Release

Spill ID: 479713 & 482375



Faded signage



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources