

Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 4523 From entrance to location

Photo # 4524 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 4525 Location



Photo # 4526 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 4527 Location

Photo # 4528 Location

Inspection Photos
Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad
Location ID: 335234



Photo # 4529 Location



Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 4531 Improperly marked deadman



Photo # 4532 Same improperly marked deadman