

Inspection Photos
Location: Red Rocks 1-16
Location ID: 484358
API # 05-071-09931



Photo 1 –Well placard

Photo 2 – Wellhead and compressor

Inspection Photos
Location: Red Rocks 1-16
Location ID: 484358
API # 05-071-09931



Photo 3 – Machine Guarding not maintained

Photo 4 – Oil stained soils

Inspection Photos
Location: Red Rocks 1-16
Location ID: 484358
API # 05-071-09931



Photo 4 – Impacted materials located @ Lat 37.461730; Long -103.518803

Photo 5 – Oil stained soils located @ Lat 37.464927; Long -103.518785