

Final Reclamation and Stormwater Inspection

March 28, 2025

Operator: BISON IV OPERATING LLC

Location ID: 311504

Location Name: BOX ELDER #2

Inspection Document #: 718600622

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BOX ELDER #2
Location ID: 311504



Photo 1. Looking west along the access road towards the well location. It appears the road has been widened and may be developed further. Also illustrating vegetation in the surrounding area.



Photo 2. Looking northwest at the well location. A large excavation is present around the wellbore. Three soil piles are located around the excavation.



Inspection Photos
Location Name: BOX ELDER #2
Location ID: 311504



May 28, 2025
340° N
ECMC

Photo 3. Construction fencing does not appear to be adequately installed to prevent entry. Soil piles do not appear to have any liners or stabilization.



May 28, 2025
226° SW
ECMC

Photo 4. The wellhead is visible at the bottom of the excavation. Erosion is present inside of the excavation and on the soil piles.



Inspection Photos
Location Name: BOX ELDER #2
Location ID: 311504



Photo 5. Looking east down the north side of the location. Erosion is present on and around the soil piles.



Photo 6. Looking east across the wellbore.



Inspection Photos
Location Name: BOX ELDER #2
Location ID: 311504



Photo 7. Looking east from the excavation. Vegetation is sparse around the well location.



Photo 8. Looking south from the well location. See photo 7 comments.

Inspection Photos
Location Name: BOX ELDER #2
Location ID: 311504



Photo 9. Google earth aerial imagery taken 03/2025. Overview of location.

