

Inspection Photos

API: 017-06784

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 5/28/2025

County: CHEYENNE



Inspection Photos



Photo 1. Drone aerial photo facing north along the former access road which now has crop cover.



Inspection Photos



Photo 2. Drone aerial photo facing north toward the abandoned location. There is insufficient crop cover.



Inspection Photos



Photo 3. Drone aerial photo facing south toward the abandoned location. There is insufficient crop cover.



Inspection Photos



Photo 4. Facing down toward the former wellsite. Agronomic soils samples will be needed to determine crop growth issues.

