

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404058084
Receive Date:
01/19/2025

Report taken by:
Laurel Anderson

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	Phone Numbers
Address: <u>1099 18TH STREET SUITE 1500</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Dan Peterson</u>	Email: <u>danpeterson@chevron.com</u>	Phone: <u>(970) 730-7281</u>
		Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 27984 Initial Form 27 Document #: 403326794

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>332956</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>JEPSEN-63N65W 2NESW</u>	Latitude: <u>40.252649</u>	Longitude: <u>-104.632535</u>	
	** correct Lat/Long if needed: Latitude: <u>40.252642</u>	Longitude: <u>-104.632524</u>	
QtrQtr: <u>NESW</u>	Sec: <u>2</u>	Twp: <u>3N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>484999</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>Jepsen-63N65W</u>	Latitude: <u>40.252977</u>	Longitude: <u>-104.633609</u>	
	** correct Lat/Long if needed: Latitude: _____	Longitude: _____	
QtrQtr: <u>NESW</u>	Sec: <u>2</u>	Twp: <u>3N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SW _____

Most Sensitive Adjacent Land Use Range Land _____

Is domestic water well within 1/4 mile? No _____

Is surface water within 1/4 mile? Yes _____

Is groundwater less than 20 feet below ground surface? No _____

Other Potential Receptors within 1/4 mile

HPH - Bald Eagle Roost or Communal Roost
Palustrine Wetland 50ft/0.09mi W, 185ft SSW, 0.10mi E, 0.08mi N
Intermittent Riverine Wetlands 0.13mi S (Gilmore Ditch)
Freshwater Pond 40ft W, 0.11mi NE
No other potential receptors are located within 1/4 mile of the Site.
Above distances are approximations.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	No Impacts	Lab Analysis
No	SOILS	See Attached Figure	Lab Analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation was conducted pursuant to ECMC Rule 911 at the JEPSSEN T3N-R65W-S2 L03 Facility and Tank Battery location.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Grab confirmation soil samples were collected from the produced water vessel(s) excavation, beneath the ground oil tank(s), and at the separator(s). Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater was encountered during remedial excavation. A grab sample was collected and analyzed for full Table 915-1 organic and inorganic constituents in groundwater (Benzene, Toluene, Ethylbenzene, Total Xylenes (BTEX), naphthalene, 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene, Chloride ion, Sulfate ion and Total Dissolved Solids (TDS).

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection at the tank battery area occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The ECMC Tank Battery and Produced Water Vessel Closure Checklists were utilized and filled out during the abandonment process.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 21

ND Highest concentration of TPH (mg/kg) _____

Number of soil samples exceeding 915-1 3

-- Highest concentration of SAR 3.38

Was the areal and vertical extent of soil contamination delineated? Yes _____

BTEX > 915-1 No _____

Approximate areal extent (square feet) 640 _____

Vertical Extent > 915-1 (in feet) 0 _____

Groundwater

Number of groundwater samples collected 0 _____

ND Highest concentration of Benzene (µg/l) _____

Was extent of groundwater contaminated delineated? Yes _____

ND Highest concentration of Toluene (µg/l) _____

Depth to groundwater (below ground surface, in feet) 9 _____

ND Highest concentration of Ethylbenzene (µg/l) _____

Number of groundwater monitoring wells installed 0 _____

ND Highest concentration of Xylene (µg/l) _____

Number of groundwater samples exceeding 915-1 0 _____

NA Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Empty rectangular box for response to the first question.

Were background samples collected as part of this site investigation?

35 background soil samples were collected from an area not impacted by oil and gas development and at similar depths and lithologies as confirmation soil samples collected at the location and analyzed for Table 915-1 metals and SSR constituents. Background soil sample analytical results were reported with elevated levels of pH, SAR, Boron and arsenic.

Background Soil Sample Analysis (mg/kg)

- Total pH at 0.5ft: Max = 5.33
- Total pH at 2ft: Max = 9.24
- Total pH at 3ft: Max = 9.53
- Total pH at 4ft: Max = 10.0
- Total pH at 5ft: Max = 9.69
- Total pH at 8ft: Max = 8.93
- Total pH at 9ft: Max = 9.00
- Arsenic at 0.5ft: Max*1.25 = 1.25
- Arsenic at 2ft: Max*1.25 = 1.59
- Arsenic at 3ft: Max*1.25 = 1.50
- Arsenic at 4ft: Max*1.25 = 2.01
- Arsenic at 5ft: Max*1.25 = 1.66
- Arsenic at 8ft: Max*1.25 = 1.89
- Arsenic at 9ft: Max*1.25 = 1.94

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____

Volume of liquid waste (barrels) _____

Is further site investigation required?

Elevated pH, EC and arsenic were observed in multiple locations at the former JEPSEN-63N65W 2NESW Tank Battery. Soil will be resampled and analyzed for full ECMC Table 915-1 suites at PWV B01 - 9ft, AST01 0.5' and AST E Wall - 2ft at the same depths where the initial elevated concentrations were observed. Noble will request an NFA be granted if the reanalyzed samples comply with the Table 915-1 concentration standard. Background samples will be used to justify elevated concentrations.

Alternatively, if the sample results exceed the Table 915-1 standards and cannot be attributed to native soil conditions via background soil characterization a minimum of five additional samples will be collected to delineate the magnitude and extent of elevated constituents.

Following completion of the delineation, Noble will submit a detailed reclamation plan to address elevated SSR constituents that includes, but is not limited to, soil analysis from adjacent undisturbed lands, revegetation techniques, site stabilization, and details of seeded species and will request NFA designation be granted under Rule 915.b: Request to leave elevated inorganics in situ.

Noble will evaluate remedial alternatives to address in situ elevated metals not attributable to background concentrations and greater than the applicable Table 915-1 concentration standards.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The organic compound exceedances observed at sample locations AST02 0.5' and N Wall 4' were removed through two separate remedial excavations. Remedial excavation confirmation soil samples were collected from each excavation and analyzed for full ECMC Table 915-1 constituents.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory analytical results indicated historical releases had occurred at the location of soil samples AST02 0.5' (Above Ground Storage Tank) and N Wall 4' (Produced Water Vault), and was reported as a historic release in Form 19 document number 403506520. The source from both historical releases were excavated and confirmation soil samples were collected and analyzed for the full Table 915-1 suite. Both excavation were completed on 10/2/2024. Refer to the attached for remedial excavation report for excavation extents.

Groundwater was additionally encountered in the PWV excavation of impacted soil at sample location N Wall 4'. A Groundwater sample was collected and analyzed for full Table 915-1 organic and inorganic constituents in groundwater (Benzene, Toluene, Ethylbenzene, Total Xylenes (BTEX), naphthalene, 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene, Chloride ion, Sulfate ion and Total Dissolved Solids (TDS). Groundwater was found to be unimpacted. Refer to the attached remedial excavation report for analytical lab report (Doc # 2410011F) for reference.

Furthermore, elevated pH was observed at sample location AST E Wall - 2ft of the above ground storage tank excavation, and elevated arsenic was observed at sample location PWV B01 - 9ft of the produced water vault excavation. Soil will be resampled and analyzed for full Table 915-1 suites at PWV B01 - 9ft and AST E Wall - 2ft at the same depths where the initial elevated concentrations were observed. Noble will request an NFA be granted if the reanalyzed samples comply with the Table 915-1 concentration standard. Background samples will be used to justify elevated concentrations. Refer to the Site Investigation Report section for further details.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

Yes _____ Excavate and offsite disposal

_____ Chemical oxidation

If Yes: Estimated Volume (Cubic Yards) _____ 191

_____ Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

No _____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

No _____ Bioremediation (or enhanced bioremediation)

No _____ Chemical oxidation

No _____ Air sparge / Soil vapor extraction

No _____ Natural Attenuation

No _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was encountered during remedial excavation activities, a grab groundwater sample was collected and analyzed for all organic compounds and inorganic parameters per Table 915-1. Groundwater was found unimpacted. Refer to the attached remedial excavation report for analytical lab report number 2410011F for reference.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Supplemental Source Mass Removal & Supplemental Site Investigation Proposal

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 04/30/2025

Proposed date of completion of Reclamation. 04/30/2028

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 01/17/2023

Actual Spill or Release date, or date of discovery. 08/22/2023

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 08/08/2023

Proposed site investigation commencement. 01/14/2024

Proposed completion of site investigation. 04/30/2024

REMEDIAL ACTION DATES

Proposed start date of Remediation. 08/09/2023

Proposed date of completion of Remediation. 04/30/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the need for a supplemental site investigation to confirm the presence of elevated SSR constituents and metals exceeding the natural variability of local background samples following decommissioning and excavation activities at the JEPSSEN-63N65W 2NESW Tank Battery. The proposed site investigation will be completed following the approval of this form.

OPERATOR COMMENT

This form serves to comply with the Rule 913.e. reporting schedule. Pending ECMC approval, the Operator will schedule and complete the additional site investigation as outlined in this proposed Site Investigation Report workplan. Supplemental Form 27s will be prepared and submitted on a quarterly schedule to provide updates and progress of the remediation until closure criteria has been achieved.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Ethan Black

Title: Consultant

Submit Date: 01/19/2025

Email: ethanb@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Jason Kosola

Date: 06/02/2025

Remediation Project Number: 27984

COA Type**Description**

0 COA	
-------	--

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

404058084	FORM 27-SUPPLEMENTAL-SUBMITTED
404058108	ANALYTICAL RESULTS
404058109	ANALYTICAL RESULTS
404058110	ANALYTICAL RESULTS
404058112	ANALYTICAL RESULTS
404062584	REMEDATION PROGRESS REPORT

Total Attach: 6 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)