

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 4784 From entrance to location




Photo # 4785 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 4786 Location



Photo # 4787 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 4788 Location




Photo # 4789 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC STI 29-7C (A29NE) Pad

Location #: 335178



Photo # 4790 Weeds/undesirable plant species near equipment



Photo # 4791 Weeds/undesirable plant species near wellheads