

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 5436 From entrance to location




Photo # 5437 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Jun 2, 2025 at 3:39:46 PM
CO

Photo # 5438 Location



Jun 2, 2025 at 3:42:45 PM
CO

Photo # 5439 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 5440 Location



Photo # 5441 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 5442 Emergency contact # on wellhead sign incorrect/# is disconnected & not in service



Photo # 5443 Emergency contact # on wellhead sign incorrect/# is disconnected & not in service

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 5444 Emergency contact # on wellhead sign incorrect/# is disconnected & not in service



Photo # 5445 Emergency contact # on wellhead sign incorrect/# is disconnected & not in service

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 5446 Emergency contact # on wellhead sign
incorrect/# is disconnected & not in service