



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Excavation containing the  
produced water flowline  
(P11SW Injection  
Waterline).

May 19, 2025 2:08:55 PM  
+39.4010N -107.7152W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Excavation containing the  
produced water flowline  
(P11SW Injection  
Waterline).

May 19, 2025 2:09:04 PM  
+39.4010N -107.7152W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Area adjacent to the point  
of release.

May 19, 2025 2:08:10 PM  
+39.4011N -107.7152W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Area adjacent to the point  
of release looking  
towards the irrigation  
ditch and Middle Mamm  
Creek.

May 19, 2025 2:09:33 PM  
+39.4009N -107.7152W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Irrigation ditch on the east side of the access road.

May 19, 2025 2:11:55 PM  
+39.4012N -107.7141W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Irrigation ditch passing  
under the access road  
from the east to the west.

May 19, 2025 2:12:20 PM  
+39.4012N -107.7141W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Irrigation ditch on the west side of the access road.

May 19, 2025 2:12:47 PM  
+39.4013N -107.7142W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Irrigation ditch on the west side of the access road.

May 19, 2025 2:13:20 PM  
+39.4014N -107.7143W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Potentially impacted  
material removed  
adjacent to the irrigation  
ditch.

May 19, 2025 2:12:45 PM  
+39.4013N -107.7142W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Potentially impacted  
material removed  
adjacent to the access  
road.

May 19, 2025 2:21:05 PM  
+39.4012N -107.7137W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Potentially impacted  
material removed  
adjacent to Middle Mamm  
Creek.

May 19, 2025 2:28:07 PM  
+39.4012N -107.7118W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Middle Mamm Creek.

May 19, 2025 2:22:48 PM  
+39.4003N -107.7120W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Middle Mamm Creek.

May 19, 2025 2:22:51 PM  
+39.4004N -107.7120W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Middle Mamm Creek.

May 19, 2025 2:24:59 PM  
+39.4007N -107.7117W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: P11SW  
Injection Waterline  
Spill/Release ID: 490230  
Inspection Date: 5/19/2025

Middle Mamm Creek.

May 19, 2025 2:25:26 PM  
+39.4009N -107.7117W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources