

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
05/19/2025
Submitted Date:
06/03/2025
Document Number:
699700474

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Heil, John On-Site Inspection
2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
2 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
,		ecmc.inspections@qb-energy.com	
Longworth, Mike		mike.longworth@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:
ECMC Environmental Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: See Initial Form 19 Doc #404205884 and Supplemental Form 19 Doc #404214966 for more information. ECMC staff John Heil and Nick Cholas conducted an Environmental Inspection of the point of release as well as the irrigation ditch and Middle Mamm Creek. An excavation containing the produced water flowline (P11SW Injection Waterline) was observed around the point of release which was approximately five (5) feet deep. ECMC staff did not observe any visible impacts on the irrigation ditch or Middle Mamm Creek. Potentially impacted material was removed adjacent to the irrigation ditch, access road and Middle Mamm Creek. See attached Photo Log for details.

Corrective Action: Comply with COAs on Form 19 Initial and Supplemental. Date: _____

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700475	20250519 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7079352