

Inspection Photos
Location Name: KENDRICK 3-31
Location ID: 326463




Inspection Photos
Location Name:KENDRICK 3-31
Location ID: 326463



Inspection Photos
Location Name: KENDRICK 3-31
Location ID: 326463

Jun 3, 2025 at 10:51:37 AM
 Durango CO 81301
 United States



Last Cal 12/18/23

DATE	CALIBRATED YES / NO	ORIFICE INSP YES / NO	ORIFICE SIZE	GAS SAMPLE YES / NO	INITIALS	COMMENTS
3/19/24	YES	YES	1.500	NO :5805	RLC	SEH CAL RPO
4/19/24	X	X	1.500	X	DG	TUBC INSPECTION
6/20/24	NO	NO	1.500	YES :5585	DB	GA-HFC
6/26/24	YES (18")	YES S/C →	1.500	YES NO	AEHTS	
9/9/24	YES	YES	1.500	:5585 NO	RLC	SEH CAL RPO
9/12/24	NO	NO	1.500	YES :5580	RH	GA-HFC
12/19/24	NO	NO	1.500	YES :5596	RH	GA-HFC
12/9/24	YES	YES	1.500	NO :5596	RT	JOU. CAL RPO
3/5/25	NO	NO	1.500	YES :5588	RS	GA HFC
3/10/25	YES (17")	YES S/C →	1.500	:5588 NO	AEHTS	