

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Location Overview – Photo #09048



Location – Photo #09056

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Location – Photo #09064



Location – Photo #09065

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Location – Photo #09066



Illegible Wellhead Sign – Photo #09049

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Illegible Wellhead Sign – Photo #09050



Illegible Wellhead Sign – Photo #09051

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Illegible Wellhead Sign – Photo #09052




Illegible Wellhead Sign – Photo #09053

Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Illegible Wellhead Sign – Photo #09054



Illegible Wellhead Sign – Photo #09055

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Illegible Wellhead Sign – Photo #09057



Illegible Wellhead Sign – Photo #09058

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Illegible Wellhead Sign – Photo #09059



Illegible Wellhead Sign – Photo #09060

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Stored Supplies/Wildlife Entry Hazard – Photo #09074



No Wildlife Egress in Well Cellar – Photo #09061

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



No Wildlife Egress in Well Cellar – Photo #09062



Unmarked Deadman – Photo #09063

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Open-Ended Line/Wildlife Entry Hazard – Photo #09072



Open-Ended Line/Wildlife Entry Hazard – Photo #09073

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Open-Ended Line/Wildlife Entry Hazard – Photo #09071



Damaged Berm Liner – Photo #09075

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/14SWSE

Location ID: 335089

Date: 5/22/2025



Damaged Berm Liner – Photo #09076