

Inspection Photos

05/07/2025

Operator: FULCRUM ENERGY OPERATING- #10805

Location ID: 324754

Inspection Document #: 712300118

Jackson County, CO

Logan Maxwell
Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Spicer Pad
Location ID: 324754



Photo 1. Photo taken from the entrance of the access road.



Photo 2. Photo taken from the entrance of the pad.

Inspection Photos
Location Name: Spicer Pad
Location ID: 324754



Photo 3. Photo taken at the tank battery. Well API # has been added to signage.



Photo 4. Photo taken from the entrance of the pad, facing west. Photo taken from the southeastern portion of the pad, facing west. Photo shows interim reclamation appears to be progressing towards 1003 standards.

Inspection Photos
Location Name: Spicer Pad
Location ID: 324754



Photo 5. Photos 5-6 taken at the southwestern and eastern sides of the wellhead. Photos illustrates stained soils. Clean up soils pursuant to Rule 912 and maintain equipment per 608.e.



Photo 6. See comments under photo 5.

Inspection Photos
Location Name: Spicer Pad
Location ID: 324754



Photo 7. Photo taken at the wellhead. Photo illustrates weedy debris around well. Comply with Rule 606.



Photo 8. Photo taken at the northern side of the wellhead, illustrating an active bird nest on the pumpjack. Operator shall implement a work zone buffer and wait until fledglings are no longer present to continue operations pursuant to Rule 902.b.