Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618

Photo # 5966 From entrance to location

Photo # 5967 From entrance to location

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618



Photo # 5968 Location

Photo # 5969 Location

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618

Photo # 5970 Location

Photo # 5971 Location

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618

Photo # 5972 Location

Photo # 5973 Location

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618

Photo # 5974 Mechanical condition - UNOCAL-ENCANA 24B-4D wellhead leak

Photo # 5975 Mechanical condition - UNOCAL-ENCANA 24B-4D wellhead leak

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618

Photo # 5976 Mechanical condition - UNOCAL-ENCANA 24B-4D wellhead leak

Photo # 5977 Mechanical condition - UNOCAL-ENCANA 24B-4D wellhead leak

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618

Photo # 5978 Ball valve on tubing tree open/wildlife & safety hazard (UNOCAL-ENCANA 24B-4D)

Photo # 5979 Ball valve on tubing tree open/wildlife & safety hazard (UNOCAL-ENCANA 24B-4D)

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618

Photo # 5980 Ball valve on tubing tree open/wildlife & safety hazard (UNOCAL-ENCANA 24B-4D)

Photo # 5981 Staining near wellhead (UNOCAL-ENCANA 24B-4D)

Inspection/Audit Photos
Location Name: QB ENERGY OPERATING LLC UNOCAL 5 Pad
Location #: 335618

Photo # 5982 Production tank dented/damaged

Photo # 5983 Production tank dented/damaged