

WELL NAME: OGALLELA 44-12 TR, API #: 071-08980, INSP. # 716301076



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.



PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: OILY WASTE IN COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 6/5/2025.